

Welding – Important Dates, Materials List, & Dress Code

New Welding Student Orientation: 2 weeks in duration – **January 13th to 23rd from 6pm to 9pm (Mon -Thur)** **First night of class for Welding Class – Monday, January 27th**

Required Materials: *Representative on site first night of orientation to offer all welder 30% discount on required materials.*

- Welding hard hat with flip action #10 dark lens
- #2 cable 10' 200 AMP Electrode Holder
- **Standard Leather Welding gloves**
- Chipping hammer
- Wire brush
- **Clear safety glasses**
- 4 1/2" Angle grinder with grinding wheels & wire wheels (optional battery operated)
- **10" Crescent Wrench**
- Pipe Wrap
- Reusable Earplugs
- Paint marker
- **Tip cleaner**
- LED Flashlight
- **Flint striker**
- Locking 'C' clamp with swivel pads
- 14" file
- Flathead Screwdriver
- Leather sleeve or green cotton jacket
- Proper Welding Clothes - to be explained at orientation
- Steel toe leather shoes
- **Cutting Shield/Face Shield**

Items highlighted in **RED** are required for the first night of orientation.

Welding Dress Code – this will be explained more during orientation

Required PPEs:

- Clear Safety Glasses
- Ear Plugs
- Standard Leather Welding Gloves
- Welding Hard Hat with flip action #10 dark lens

Required Welding Clothes:

- Outer Shirts: (your choice)
 - Flame Retardant Shirt
 - LAPCO Shirt with snap buttons (100% cotton)
 - Flame Retardant green cotton welding jacket
 - Full leather jacket
 - Leather cape, sleeve, and bib
 - Nomex Shirts or Jumpsuit
- Under Shirts:
 - **MUST be 100% cotton – NO POLYESTER OR BLENDS ALLOWED**
- Pants:
 - Blue Jeans without holes, strings hanging down, and stretch material added
 - Nomex Pants or Jumpsuits
 - FR Jeans/Pants
- Shoes:
 - **Must be leather shoes with steel toes – NO rubber boots or tennis shoes**

Non-compliance to new PPE and Clothing Policy will result in dismissal from class that night with a mandatory absence given.