



Welding Tool list

- Welding hard hat with flip action #10 dark lens
- #2 Cable 10' 200 AMP Electrode holder
- Standard Leather Welding Gloves
- Chipping Hammer
- Wire Brush
- Clear Safety Glasses
- 4 ½" Angle Grinder
- 4 of each type of Grinding Wheels
 - Wire Buffing Wheel
 - Grinding Wheel (4 ½" thick by ½" with a ⅝" shank)
- 10" Crescent Wrench
- Pipe Wrap
- Reusable Earplugs
- Paint Marker
- Tip Cleaner
- Small LED Flashlight
- Flint Striker
- Lock 'C' Clamp with Swivel Pads
- 14" File
- Flathead Screwdriver
- Leather Sleeve or Green Cotton Jacket
- Proper Welding Clothes - to be explained in class
- Steel Toe Leather Shoes
- Cutting Shield/Face Shield
- 2lb Drilling Hammer



Dress Code

Required PPEs:

- Clear Safety Glasses
- Ear Plugs
- Standard Leather Welding Gloves
- Welding Hard Hat with flip action #10 dark lens

Required Welding Clothes:

- Outer Shirt (your choice):
 - Flame Retardant Shirt
 - LAPCO Shirt with Snap Buttons (100% cotton)
 - Flame Retardant Green Cotton Welding Jacket
 - Full Leather Jacket
 - Leather Cape, Sleeve or Bib
 - Nomex Shirts or Jumpsuit
- Under Shirt:
 - **Must be 100% cotton - no Polyester or Blends allowed**
- Pants:
 - Blue jeans without - holes, stringing hanging down, and/or stretch material added
 - Nomex Pants or Jumpsuits
 - FR Jeans/Pants
- Shoes:
 - **Must be leather shoes with steel toes - NO rubber boots or tennis shoes**

